

Specific Purpose Blowers



Fig. A A064



Fig. B A134



Fig. C A145



Fig. D A141



Fig. E A148

NEW
NEW

NEW

BLOWERS FOR HIGH EFFICIENCY FURNACES						
Model	Fig.	Volts	Amps	Motor Type	No. of Speeds	Reference No.
A064	A	115	.7	S.P.	1	Heil Quaker 610672, 7021-5043, 7021-7102
A134•	B	115	1.5	S.P.	1	InterCity Products 7021-9335/ 7021-8735, 7021-9499, 7021-8736, 7021-7700
A145^•	C	115	.7	P.S.C.	1	InterCity Products 7062-4061
A141•	D	115	1	S.P.	1	InterCity Products 7021-8741, 7021-8742, 7021-9188, 7021-9498
A148	E	208-230	.5	S.P.	1	InterCity Products 7021-7617, 7021-9237
A151	F	230	.3	S.P.	1	InterCity Products HQ1050144
A135	H	120	.7	S.P.	1	Lennox 7021-8812, 7021-8819
A138	G	120	.7	S.P.	1	Lennox 7021-8657, 7021-8825
A163	I	115	1.8	S.P.	1	Lennox 7021-9450
A164	J	120	.8	S.P.	1	Lennox 7021-9593
A169	K	230	.75	S.P.	1	InterCity Products 7021-10048, 7021-10580
A170	L	115	2.3	S.P.	1	InterCity Products, 7021-10299, 7021-10702
A081*+•	H	230	.5	S.P.	1	Magic Chef, HWC series 48HWC24A, 48HWC181, 35HWC181, 60HW, 60HWC24A, 60HWC181, 48HW, 60HWC30A, 66HWC18A, 36HWC241, 66HW, 60HWC241, 66HWC181, 66HWC241, 60HWC301, 48HWC241, 66HWC301, 48HWC18A, 60HWC18A, 36HWC18A, 66HWC24A, 36HW, 36HWC24A
A085	I	230	.7	S.P.	1	AO SMITH 464, JOHNSON FURNACE

* Stainless Steel shaft • Ball bearing motor ^ 4MFD, 250 VAC Capacitor included
+ Replacement For Airease, Armstrong and Magic Chef



Fig. F A151



Fig. H A081



Fig. J A164



Fig. L A170



Fig. G A135, A138



Fig. I A163, A085



Fig. K A169

Products on this page are NOT SUITABLE for unattended equipment unless indicated by ► symbol. See inside back cover for additional information.

See pages 48 through 71 for OEM direct replacement models.