













# One-On-One™ Direct Replacement Motors



	MARS NO.	MFG. NO.	HP	VOLTS	RPM/SPEEDS	ROT	AMPS	DIMENSIONS		
								A	B	C
<b>Fedders (con't)</b>										
	<b>D186</b>	-	1/20	460	1500/1	CW SE	0.4	2.33	2.88	-
	Shaded pole, sleeve bearing, 5/16 inch dia. shaft									
	<b>Replaces:</b> Roof Top A/C									
										
	<b>D1012</b>	-	1/15 - 1/20 - 1/25	115	1550/3	DS	2.3 - 1.9 - 1.6	3.00	3.38	3.00
	Shaded pole, sleeve bearing, 3/8 inch dia. shaft									
	<b>Replaces:</b> RMR, RY1302, 5206-00025-001, Y24CW50, 7190-0163									
										
	<b>D1010</b>	-	1/8 - 1/12 - 1/15	115	1050/3	DS	4.4 - 3 - 2.3	3.33	3.38	2.75
	Shaded pole, sleeve bearing									
	<b>Replaces:</b> Window AC Motor; S196-20-2									
										
	<b>D1011</b>	-	1/6 - 1/12 - 1/15	208 - 230	1050/3	DS	2.5 - 1.6 - 1.2	3.33	3.25	2.75
	Shaded pole, sleeve bearing									
	<b>Replaces:</b> Window AC Motors; S196-42-1, S296-161-3									
										
	<b>D884</b>	-	1/6 - 1/8 - 1/10	115	1050/3	DS	2.3 - 2 - 1.8	5.00	3.75	4.00
	PSC, sleeve bearing									
	<b>Replaces:</b> S196-59-1, 2:72-1, 2:73-1, 2:74-1,2,3									
										
	<b>D882</b>	-	1/5	230	1080/1	CW SE	1.5	4.25	3.88	-
	PSC, sleeve bearing, 7.5@370V capacitor installed									
	<b>Replaces:</b> Condenser Fan; S196-179-1									
										

ONE-ON-ONE