



FASCO Motor Scope Selection Guide

SHADED POLE MOTORS - 3.3" DIAMETER

FASCO MODEL#	DIA.	HP	VOLTS	RPM	SPD.	AMPS	ENCLOSURE	ROT.	BRNG.	SHAFT DIM.
D1121	2.3	1/20	208-230	1550	1	1.0	Open Vent.	CW	SLV	5/16 X 2-1/2
D200	3.25	1/85	115	3000	1	0.6	Open Vent.	CW	SLV	2-3/8 X 1/4 X 3/4
D201	3.25	1/85	115	3000	1	0.6	Open Vent.	CCW	SLV	1/4 X 1-3/8
D107	3.3	1/160	208-240	600	1	0.5	Open Vent.	CCW	SLV	5/16 X 1
D408	3.3	1/150	115	3000	1	0.5	Open Vent.	CW	SLV	1/4 X 1-1/2
D129	3.3	1/125-1/200	115	1500	2	.4-.3	Open Vent.	DS	SLV	3-1/4 X 1/4 X 3-1/4
D229	3.3	1/100	115	3000	1	0.55	Open Vent.	CCW	SLV	1/4 X 3-1/2
D230	3.3	1/100	115	3000	1	0.55	Open Vent.	CW	SLV	1/4 X 3-1/2
D540	3.3	1/100	115	1500	1	0.6	Tot. Encl.	CW	SLV	1/4 X 2-1/4
D541	3.3	1/100	115	1500	1	0.6	Tot. Encl.	CCW	SLV	1/4 X 2-1/4
D1109	3.3	1/100	115	1500	1	0.65	Tot. Encl.	CCW	SLV	1/4 X 1-1/4
D1162	3.3	1/100	115	1500	1	0.6	Open Vent.	REV	SLV	5/16 X 1
D1119	3.3	1/90	240	1500	1	0.34	Open Vent.	CCW	SLV	1/4 X 1-1/2
D202	3.3	1/85	115	3000	1	0.6	Open Vent.	CW	SLV	1/4 X 2-1/4
D228	3.3	1/80	115	3000	1	0.8	Open Vent.	CW	SLV	1/4 X 2
D122	3.3	1/80	115	1500	1	0.6	Tot. Encl.	CW	SLV	1/4 X 2-1/4
D123	3.3	1/80	115	1500	1	0.6	Tot. Encl.	CCW	SLV	1/4 X 2-1/4
D431	3.3	1/80	230	1550	1	9 Watts	Tot. Encl.	CCW	SLV	HUB
D120	3.3	1/70	115	1500	1	0.7	Open Vent.	CW	SLV	1/4 X 2-1/4
D121	3.3	1/70	115	1500	1	0.7	Open Vent.	CCW	SLV	1/4 X 2-1/4
D167	3.3	1/70	115	1500	1	0.7	Open Vent.	CW	SLV	1/4 X 3
D169	3.3	1/70	115	1500	1	0.7	Open Vent.	CCW	SLV	1/4 X 3
D402	3.3	1/60	115	3000	1	0.75	Tot. Encl.	CW	SLV	1/4 X 1-3/4
D403	3.3	1/60	115	3000	1	0.75	Tot. Encl.	CCW	SLV	1/4 X 2-1/4
D182	3.3	1/60	115	1500	1	0.6	Tot. Encl.	CW	SLV	5/16 X 2-1/4
D1134	3.3	1/50-1/65-1/80	115	1500	3	1.1-8-.6	Open Vent.	CW	SLV	1/4 X 1-3/4
D1139	3.3	1/50-1/80-1/125	115	1500	3	0.88	Open Vent.	CW	SLV	2-1/2 X 5/16 X 1-1/8
D609	3.3	1/50	115	1500	1	0.9	Open Vent.	CCW	SLV	1/4 X 2-1/4
D603	3.3	1/50	115	1500	1	0.9	Open Vent.	CW	SLV	1/4 X 2-3/8
D124	3.3	1/50	115	1500	1	0.75	Tot. Encl.	CW	SLV	1/4 X 2-1/4
D125	3.3	1/50	115	1500	1	0.75	Tot. Encl.	CCW	SLV	1/4 X 2-1/4
D601	3.3	1/50	115	1500	1	0.9	Tot. Encl.	CCW	SLV	1/4 X 2-1/4
D602	3.3	1/50	115	1500	1	0.9	Tot. Encl.	CW	SLV	1/4 X 2-1/4
D418	3.3	1/50	115	1550	1	1.1	Open Vent.	CW	BALL	1/4 X 3
D608	3.3	1/50	230	3000	1	0.6	Open Vent.	CW	SLV	1/4 X 1-5/16
D624	3.3	1/50	230	1500	1	0.4	Tot. Encl.	CW	SLV	1/4 X 2-1/4
D128	3.3	1/40-1/50-1/80	115	1500	3	1.3-9-.6	Open Vent.	DS	SLV	4 X 5/16 X 4
D205	3.3	1/40-1/70	115	3000	2	1-.5	Tot. Encl.	DS	SLV	3 X 1/4 X 3
D203	3.3	1/40	115	3000	1	1	Open Vent.	CCW	SLV	1/4 X 2-1/4
D126	3.3	1/40	115	1500	1	1.1	Open Vent.	CW	SLV	5/16 X 2-1/4
D127	3.3	1/40	115	1500	1	1	Open Vent.	CCW	SLV	5/16 X 2-1/4
D106	3.3	1/40	115	1500	1	0.9	Open Vent.	CCW	SLV	1/4 X 1-3/4
D130	3.3	1/40	115	1500	1	1	Open Vent.	CW	SLV	5/16 X 4-1/8
D131	3.3	1/40	115	1500	1	1	Open Vent.	CCW	SLV	5/16 X 2-1/4
D415	3.3	1/40	115	1550	1	1.1	Open Vent.	CCW	BALL	1/4 X 3
D1192	3.3	1/40	115	3000	1	0.7	Open Vent.	CCW	SLV	5/16 X 1-1/2
D1167	3.3	1/40	208-230	3000	1	0.55	Open Vent.	CCW	SLV	5/16 X 1
D190	3.3	1/40	230	1500	1	0.6	Open Vent.	CW	SLV	1/4 X 2-1/4
D330	3.3	1/40	230	1500	1	0.5	Open Vent.	CW	SLV	5/16 X 2-1/4
D1191	3.3	1/40	460	3200	1	0.37	Open Vent.	CCW	BALL	1/4 X 2-1/2
D105	3.3	1/37	115	1500	1	0.94	Open Vent.	CCW	SLV	1/4 X 1-1/2
D534	3.3	1/35-1/100	115	1500	1	1.4-.5	Tot. Encl.	CW	SLV	1/4 X 1
D477	3.3	1/35	208 / 230	1550	1	0.75	Open Vent.	CCW	SLV	5/16 X 1-5/8
D1196	3.3	1/33	115	3200	1	1.5	Open Vent.	CCW	SLV	5/16 X 2-1/3

FASCO

